



Thermography Report



Any Customer
Anytown, NH

Thermography date: (Date)

Weather: (Sunny)




Picture 1. Captured at: Left front



Moisture Content: High moisture content
Comment: Elevated moisture in the yellow and green areas of area #1 and #2. The yellow sections have moisture than the green.
Recommendation: Recommend removing the siding to inspect and repair as needed.

Picture 2. Captured at: Right front



Moisture Content: High moisture content
Comment: Elevated moisture in the lighter areas of #1 and #2.
Recommendation: Recommend removing the siding to inspect and repair as needed.